# NEW HEAVY DUTY SOLUTIONS

### EXHAUST GAS TEMPERATURE SENSOR

AFTERMARKET EXCLUSIVE

REPLACE JUST THE BUNG, SAVE THE EXHAUST PIPE



**904-9917**Kenworth T800 2007-06,

Kenworth W900 2007-06, Peterbilt 379 2007-06 **OE Number:** O211035

#### EGT sensors frequently seize in the exhaust bung, making replacement difficult and damaging the bung

 This unique repair solution includes a sensor, new bungs, weld-on plates, zip ties, and a convenient bung repair kit, just in case

## EXHAUST GAS RECIRCULATION (EGR) COOLER

AFTERMARKET EXCLUSIVE

HALF A MILLION REPAIR OPPORTUNITIES



and function of the original EGR cooler in specified trucks

• Engineered to match the fit

 Subjected to rigorous heat transfer testing, burst testing and vehicle try-on testing to ensure fit and reliability

#### 904-5175

Crane Carrier Company 2016, Freightliner 2017-13, Mack 2017-14, Paccar 2017-14, Volvo 2017-13

**OE Number:** 2881963NX, 2882147, 2882147NX, 4309207, 4390207NX, 4309449, 4309449NX, 4309498, 4352365, 4352365NX, 4352365RX

#### **WIRING HARNESSES**

**AFTERMARKET EXCLUSIVES** | COST-EFFECTIVE RELIABLE REPLACEMENTS



**311-0019** 2016-14 Cummins ISX Engines **OE Number:** A0691576089

# 5

**311-0014** 2018-14 Cummins ISX Engines **OE Number:** 4352672

- Designed to match the fit and function of the original harness on specified applications
- Quality engineered to be a reliable replacement for an original harness that is missing, failed or damaged due to corrosion

• Designed to match the fit,

of the right side factory

· Ideal, cost-effective

replacement for a malfunctioning or

interior door handle latch on specified Volvo trucks

function and performance

#### **ENGINE OIL DIPSTICK**

VERSATILE APPLICATIONS

COST-EFFECTIVE RELIABLE REPLACEMENT



- Designed to match the fit and function of an original equipment dipstick in various applications
- Features level marks that are clearly distinguished and properly gauged for accuracy

#### INTERIOR DOOR HANDLE LATCH

COST-EFFECTIVE RELIABLE REPLACEMENT

SEAMLESS INSTALLATION



broken latch

760-5119

Volvo VHD 2022-06, Volvo VNL 2022-06, Volvo VNR 2022-18 (Right, Internal Latch)

**OE Number:** 1063328, 20570722





## NEW HEAVY DUTY SOLUTIONS

#### MORE COVERAGE FROM OUR GROWING LINE OF SENSORS

#### INTAKE MANIFOLD/COOLANT TEMPERATURE SENSOR

COST-EFFECTIVE RELIABLE REPLACEMENT



904-7137

Various Models, 2004-2011 with Cummins ISX, ISB, and ISM Engines
OE Number: 4088832, 4088833

- Manufactured to exacting specifications and designed to match the fit and function of the original equipment sensors on specified vehicles
- Engineered to help accurately monitor critical engine systems when an original sensor has failed from heat, fatigue, or internal component damage

#### **COOLANT TEMPERATURE SENSOR**

AFTERMARKET EXCLUSIVE



904-7471

Mack 2005-99 E7 and EM7 Engines **OE Number:** 20705959, 64MT2103

#### **COOLANT TEMPERATURE SENSOR**

COST-EFFECTIVE RELIABLE REPLACEMENT



904-7549

Ford 2009-04, IC Corporation 2016-04, International 2017-04 (Sensor Only)

OE Number: 1836537C91

#### COOLANT TEMPERATURE SENSOR

AFTERMARKET EXCLUSIVE



904-7585

IC Corporation 2016-12, International 2016-08 **OE Number:** 1881015C92

#### **OIL TEMPERATURE SENSOR**

COST-EFFECTIVE RELIABLE REPLACEMENT



904-7248

Various Models, 2000-89 with Detroit Diesel Series 60 Engine

OE Number: 23518092

